



AIR160

AIR-PURIFIER

AIR160. Reference card

MAXIMA HOSPITAL, VELDHOVEN, THE NETHERLANDS

- 1 **Location** Waiting area / lounge
- 2 **Problem** Potential threat of infestation
- 3 **Installed** 2x Air 160
- 4 **Treatment** 50 m³ / hr per unit
- 5 **Special** Removal of solid particles was decisive
- 6 **Reduction achieved** Yes
- 7 **Installed since** Jan 2018

Comment

Both the installation company and the client (hospital) are happy with the performance of the unit.



TRANSPORT DE HAAN, NIJKERK - THE NETHERLANDS

- 1 **Location** Office building, logistic department
- 2 **Problem** General improvement of air quality
- 3 **Installed** 5x Air 160
- 4 **Treatment** 100 m³ / hr per unit
- 5 **Special** Air quality was very poor, people suffering from hay fever
- 6 **Reduction achieved** Yes
- 7 **Installed since** Nov 2017

Comment

Logistic staff feel that the air has improved significantly and that hay-fever is less of a problem.

AMSTELRING AMSTERDAM, THE NETHERLANDS

- 1 **Location** Rest area of a retirement home
- 2 **Problem** General improvement of air quality
- 3 **Installed** 3x Air 160
- 4 **Treatment** 100 m³ / hr per unit
- 5 **Special** Air quality was poor. Most residents had health issues and the improved air reduces a risk factor of air-borne infection
- 6 **Reduction achieved** Yes
- 7 **Installed since** Dec 2017

Comment

Residents and staff are happy with the units and no longer complain of poor air quality.

FISH, VELDHOVEN - THE NETHERLANDS

- 1 **Location** Fish store & restaurant
- 2 **Problem** General improvement of air quality
- 3 **Installed** 1 x Air 160
- 4 **Treatment** 100 m³ / hr per unit
- 5 **Special** Improve hygiene conditions and reduce microbial activity in the air
- 6 **Reduction achieved** Yes
- 7 **Installed since** Jun 2018

Comment

Logistic staff feels that the air has improved significantly and that hay-fever is less of a problem, when working in the office.

KARKO GLASS, THE NETHERLANDS

- 1 **Location** Office building
- 2 **Problem** General improvement of air quality
- 3 **Installed** 2 x Air 160
- 4 **Treatment** 100 m³ / hr per unit
- 5 **Special** Air quality was very poor, people suffering from pollen & bad smells
- 6 **Reduction achieved** Yes
- 7 **Installed since** Jun 2018

Comment

Staff feel that the air has improved significantly and that pollen are less commonly present.

